

Brookville Equipment Corporation
Product Information Bulletin 56 (05-20-02)
Series 530 Caliper Brake
Potential Housing bolt Problem

Purpose:

Some brake caliper units (part # 14-9099) may have been assembled with bolts of insufficient strength. The bolts may fail by breakage or back out while in service. The units have been shipped since January 1, 2000. If the date code is not visible on the ID tag or the tag is missing, the bolts may be identified by lines on the head of the cap screws. The 4 housing bolts must have 3 or more bars embossed into the head of the bolt.

Action:

If the bolts are not the correct hardness, please request conversion kit # 02-500-232. Complete bolt replacement instructions are included with the kit. If you have any questions, please contact Andy Cable – Director of Quality at 1-814-849-2000.

Date code affected:

00 C 000 to 02 C 015

Verification:

Please contact Parts Sales (contact@brookvilleservices.com) for the kits. The correct quantity of kits will be sent to you upon request.