

Brookville Equipment Corporation
Product Information Bulletin 57 (09-18-03)
Brookville Part Number 02-15035
Wear Indicator Pin Upgrade

Purpose:

On a small percentage of brake assemblies, BEC P/N 02-15035, the wear indicator pin has come loose. This condition may result in a loss of fluid, which potentially could lead to a lock up of the brakes.

Action:

We recommend that the wear indicator pin be replaced. BEC customer service will ship, at no charge, an upgrade kit (PTT-381-66) for each brake assembly that was either installed or sold at Brookville Equipment Corporation prior to 9/18/03.

Unit Serial Numbers Affected:

8814, 8815, 8816, 8817, 8818, 8819, 8820, 8821

Sales Order Numbers Affected:

011357

Verification:

Brookville Equipment Corporation will contact each of the affected customers with regards to the receipt and installation of the upgrade kits. If you have any questions, please contact Andy Cable – Director of Quality at 1-814-849-2000.