

**Brookville Mining Equipment Corporation**  
**Product Information Bulletin 51 (02-15-01)**  
**Brookville Model 1260B-Xlow**  
**Joystick Relocation Procedure**

**Purpose:**

On Brookville Model 1260B-Xlow units, there may be a possibility that when the joystick in the front operators station is rotated to the maximum tram position, an operators hand could activate the E-stop switch.

**Action:**

This possibility can be eliminated by contacting Brookville and ordering a free modification kit (12-0947). This kit contains two new mounts for both the front and rear joysticks, and instructions for mounting both joysticks in a new location. The new mounting location eliminates the possibility of activating the E-Stop switch.

**Serial Numbers Affected:**

8310, 8313, 8355, 8361, 8362, 8363, 8364, 8399, 83100, 8437, 8438, 8440, 8441

**Verification:**

Brookville Mining Equipment Corporation Service Manager will contact each mine with the above units, and ship the modification kit to each mine. After receiving and installing the kit, the mines are asked to return the joystick relocation modification form.

# Joystick Relocation Verification Form

Please complete and fax back this modification form after the joystick locations have been changed.

Person Completing Modification Form:

\_\_\_\_\_

Printed Name

\_\_\_\_\_

Signature

Title:

Name of Company:

Address:

Phone:

( ) Our company has made the modification for relocating the joysticks based on drawing 6-3275B

Machine Serial Number:

Please Fax Back: Attention Harry Reitz  
Fax Number: 814-849-2010  
Email: [hreitz@brookvillecorp.com](mailto:hreitz@brookvillecorp.com)