

Brookville Mining Equipment Corporation
Product Information Bulletin 52 (02-16-01)
Brookville Model 1260B-Xlow
Safety Chain Relocation Procedure

Purpose:

On Brookville Model 1260B-Xlow units, the safety chains were initially designed to be mounted on the outside of the operator's compartment. It has been proven that mounting the safety chains on the inside of the operators compartment is a better design.

Action:

We are recommending that the safety chains be remounted inside the operators compartment. New (free of charge) safety chain kits (12-0948) contain new safety chains, bolts, and mounting drawings. The mounting drawing shows the different canopy heights and the recommended mounting heights of the safety chains.

Serial Numbers Affected:

8310, 8313, 8355, 8361, 8362, 8363, 8364, 8399, 83100, 8437, 8438, 8440, 8441

Verification:

Brookville Mining Equipment Corporation Service Manager will contact each mine with the above units, and ship the modification kit to each mine. After receiving and installing the kit, the mines are asked to return the safety chain relocation modification form.

Safety Chain Relocation Verification Form

Please complete and fax back this modification form after the safety chain locations have been changed.

Person Completing Modification Form:

Printed Name

Signature

Title:

Name of Company:

Address:

Phone:

() Our company has made the modification for relocating the safety chains based on drawing 06-1950B

Machine Serial Number:

Please Fax Back: Attention Harry Reitz
Fax Number: 814-849-2010
Email: hreizt@brookvillecorp.com